

Solving environment-related business problems worldwide

www.deltaenv.com

27141 Aliso Creek Road • Suite 270 Aliso Viejo, California 92656 USA 949.362.3077 800.477.7411 Fax 949.362.0290

January 25, 2006

Mr. Jay Bento Santa Ana Fire Department Underground Storage Tank Division 1439 South Broadway Santa Ana, California 92707

Sent via UPS

Subject:

Well Destruction Report ARCO Facility No. 6085 1222 East First Street Santa Ana, California

Dear Mr. Bento:

Delta Environmental Consultants, Inc. (Delta), on behalf of Atlantic Richfield Company, has prepared this *Well Destruction Report* detailing the proper destruction of seven soil vapor extraction (SVE) wells at ARCO Facility No. 6085, (the Site, Figure 1) located at 1222 East First Street, Santa Ana, California. These wells were properly destroyed at the request of Orange County Health Care Agency (OCHCA) in order to facilitate this site for case closure.

WELL DESTRUCTION ACTIVITIES

On December 2, 2005 Delta was on-site to oversee the destruction of seven SVE wells (B-6, B-7, B-8, B-9, B-10, VW-1, and VW-2. A site map showing the locations of all wells is provided as Figure 2. Well construction details for all wells are provided in Table 1. Cascade Drilling, Inc. of Norwalk, California (License No. C57-71510) was contracted to provide the equipment and personnel required to conduct the field activities. The invoice for field activities and materials used is included in Attachment A. Prior to initiating field activities, a well destruction permit was obtained from the OCHCA (Attachment B), and Underground Service Alert was notified.

SVE wells B-7, B-9, B-10, VW-1 and VW-2 were properly destroyed by pressure-grouting. Wells B-7, B-9, B-10, VW-1, and VW-2 were pumped under pressure with approximately 10, 30, 30, 40, and 50 gallons of grout, respectively. The upper 2 feet of the each well was filled with bentonite chips and capped with concrete to match the surrounding surface. The wells could not be over-drilled due to the close proximity of each well to dispensers, pipelines or underground storage tanks.

Wells B-6 and B-8 were unable to be located; however, both wells B-6 and B-8 were once connected to the former SVE system via lateral piping. During well destruction activities approximately 35 gallons of bentonite grout was pumped under pressure into the SVE manifold and into the lateral lines of well B-6 and B-8. The



Well Destruction Report ARCO Facility No. 6085 Santa Ana, California Page 2

volume of grout used, for each well destruction, was greater than the calculated volume of grout required to fill each SVE lateral line and properly destroy each well.

REMARK/SIGNATURES

The recommendations contained in this report represent Delta's professional opinions based upon the currently available information and are arrived at in accordance with currently acceptable professional standards. This report is based upon a specific scope of work requested by the client. The Contract between Delta and its client outlines the scope of work, and only those tasks specifically authorized by that contract or outlined in this report were performed. This report is intended only for the use of Delta's Client and anyone else specifically listed on this report. Delta will not and cannot be liable for unauthorized reliance by any other third party. Other than as contained in this paragraph, Delta makes no express or implied warranty as to the contents of this report.

If you have any questions or comments concerning this report, please contact the undersigned at (949) 860-0209.

Sincerely,

DELTA ENVIRONMENTAL CONSULTANTS, INC.

Christopher A. Ota Project Manager Bryan Van Wagner California Professio

California Professional Geologist No. 5820

California Hydrogeologist No. 295

Attachments:

Figure 1

Site Location Map

Figure 2

Site Map

Table 1

Well Construction Details

Attachment A

Cascade Invoice

Attachment B


OCHCA Well Destruction Permits

cc:

Mr. Bobby Lu, Atlantic Richfield Company, La Palma, California

Ms. Valerie Jahn-Bull, CRWQCB – Santa Ana Region, Riverside, California

Mr. Dan Yokayama, OCHCA - Santa Ana Region, Riverside, California



REPRODUCED WITH PERMISSION
GRANTED BY THOMAS BROS. MAPS ®.
THIS MAP IS COPYRIGHTED BY THOMAS
BROS. MAPS ® IT IS UNLAWFUL TO COPY
OR REPRODUCE ALL OR ANY PART THEREOF,
WHETHER FOR PERSONAL USE OR RESALE,
WITHOUT PERMISSION.



- X -

FIGURE 1 SITE LOCATION MAP ARCO FACILITY NO. 6085 1222 EAST FIRST STREET SANTA ANA, CA.

PROJECT N AMOO-6	0. 29	DRAWN BY
FILE NO. 8-616-		PREPARED BY M. LUCAS
DATE 30 May 02	REV.	REVIEWED BY



FIRST STREET PLANTER 8-7 **⇔** B−11 в-6-ф B-8-Ò PUMP ISLANDS B-10 ARCO AM/PM FACILITY NO. 6085 PUMP ISLANDS -**Ò**-B−9 EXISTING UST'S FORMER UST'S PROPERTY LINE 30' **SCALE** LEGEND FIGURE 2 DESTROYED WELL LOCATION SITE MAP B-12 • ARCO FACILITY NO. 6085 VERTICAL SOIL BORING LOCATION

1222 EAST FIRST STREET SANTA ANA, CA.

PROJECT N	0.	DRAWN BY
G0B5Y	<u> </u>	K. MARTIN
FILE NO.		PREPARED BY
8-616-	05	C. OTA
DATE 23 JAN 06		REVIEWED BY



(q:\bpwest\socal\6085\well construction details table - january 2006.xls.xls)

TABLE 1

WELL CONSTRUCTION DETAILS ARCO FACILITY NO. 6085 1222 EAST FIRST STREET SANTA ANA, CALIFORNIA

Well I.D.	Date Construction Completed	Well Type	Total Depth (feet bgs)	Screen Interval (feet bgs)	Casing Diameter (inches)
, c	00/20/00	Vonce Detection	01	5 - 10	4
ρ-0 1	08/03/93	Vanor Extraction	7.5	3 - 7.5	. 4
- 8-B	08/03/93	Vapor Extraction	9.5	4 - 9.5	4
6-8 B-9	08/03/93	Vapor Extraction	17	7-17	4
B-10	08/02/93	Vapor Extraction	17	7-17	4
VW-1	08/02/93	Vapor Extraction	22	7 - 22	4
VW-2	08/02/93	Vadose	36	26 - 36	4
1					

NOTES:

Below ground surface

bgs

ATTACHMENT A

Cascade Invoice



L.A.: 11250 Firestone Norwalk, CA 90650 (562) 929-8176 PH (562) 863-9534 FAX Seattle: PO Box 1184 Woodinville, WA 98072 (425) 485-8908 PH (425) 485-4368 FAX Portland: 15635 SE 114th Clackamas, OR 97015 (503) 775-4118 PH (503) 775-4099 FAX Sacramento: 3632 Omec Cir. Rancho Cordova, CA 95742 (916) 638-1169 PH (916) 638-5611 FAX

CLIENT: T)	TFA	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			C1	IERI	T nn 4. 1.00	2			
CLIENT: Delta CLIENT P.O. #: 6085											
JOB LOCATION: 1722 & First St DIG ALERT#: DATE: 12 105 HOURS HOURS											
	FCT#• v	105-670.01					f/i		START	STOP	HOURS TOTAL
WELL# DEPTH							A MA CHOD THE		530	545	TOTAL
BORING# DRILLE		SCRIPTION	1 O	F WO	RI	<	TRAVEL TO SIT		545	646	
	-	N + 5	1-4	ment !	رد		INAVEL TO OTT	<u> </u>	700	73.0	
-	1 < 1			PRICELLE					750	A80	
Va. 1 72	- F								733 පි . විට	(2)0	
1/N-1 83	120	P.G. VW-Z 33."						,,			
17 5.2	r	MOJE SEFUP						1000			
	Try to locate other wells Did not find Am.						1000	100			
3-19-19							1100				
	mover setup										
B-10 10		Pen. 13-10,10'									
	move set up										
8-77	-	RG. B-7',7							1200	1200	
		Chne no 4 L	ord u	0					1		
				·					1200	115	
TOTAL	$\prod_{\tau \leftarrow \tau}$	AL OLIADORADIE		01100			TRAVEL TO SH	0P			
FOOTAGE TOTAL CHARGEABLE RIG HOURS					P.M. SHOP TIM						
				CAS	7 1		MATERIALS				
RIG#	103	COMPRESSOR/JACK HAMMER		DIAMETER	2"	4º	ITEM	ату.	וו	ГЕМ	QTY.
FLATBED TRUCK #	307	FORKLIFT / HOPPER		20 FT. SCREEN	$\downarrow \downarrow$	_	SAND		WELL COVE	ER	
FLATBED TRUCK #	<u> </u>	CONT. SAMPLER FOOTAGE		10 FT. SCREEN	11		READY MIX	d	MONUMENT		
TRAILER #	203	# OF HYDRO PUNCHES		5 FT. SCREEN		1	QUICK SET	1	BARREL	<u>.S</u>	1
# OF SAW CUTS	 	SNOW FENCE RENTAL	15	20 FT. BLANK	-	4	PORTLAND		AUGER PLU		
# OF CORE CUTS	-			10 FT. BLANK		Д	BENTONITE GROUT	8	SAMPLE	LINERS	
# OF BULL DOG	 			5 FT. BLANK		4	BENTONITE CHIPS	5	HOLE COVE	R PLATES	
BOBCAT				SLIP CAP	1	4	BENTONITE POWDER		CONES/DEL	INEATORS	47-
CREW WITH PERDIEM		DEPTH TO WATER		THREADED CAP	$\parallel \parallel$	\dashv	BENTONITE PELLETS		TRAFFIC CO	ONTROL	
FLITOILWI	<u>. L </u>		TOTAL	LOCKING CAPS	11	_	COATED PELLETS		PLASTIC S	HEETING	
NAME		SIGNATURE	TOTAL HRS.	SPARGE TIP	-	+	BENTONITE GRANULAR		CME TEETI		
MWAteres						-+	ASPHALT PATCH		TIPS & SCR		
Cy Chonzali	22	····			$\parallel \parallel$	+	KENAMETALTEETH		CORE BOX		
M DAVIS					\parallel	+	SAMPLER SHOE		GUARD POS		
FVI DAVIS	-			<u> </u>		-	BIT REPAIR		ENCOR SAI	MPLING	
DEMARKS											
REMARKS		, , , , , , , , , , , , , , , , , , ,						-			

CLIENT SIGNATURE

Mich DAG OPERATOR SIGNATURE

ATTACHMENT B

OCHCA Well Destruction Permits

APPLICATION FOR WELL DESTRUCTION PERMIT

ORANGE COUNTY HEALTH CARE AGENCY ENVIRONMENTAL HEALTH DIVISION 2009 E. EDINGER AVENUE SANTA ANA, CA 92705-4721) (714) 697-9800 . FAX: (714) 972-0749

OTY Santa ana	DATE 11 29 05
WELL LOCATION (ADDRESS IF AVAILABLE) 12-22 East First Street, Sant	
NAME OF WELLOWNER AHANTY RICHARD COMPANY	Ana, CA - ARCO GOBS NAME OF CONSULTING FIRM Delta Environmental BUSINESS ADDRESS 27141 Aliso Creek Pd, Ste 270
ADDRESS 4 Center Dointe	BUSINESS ADDRESS 27141 Aliso Creek Pd, Ste 270
CITY	OITY ZIP ISLEPHONE 177 302 020
NAME OF DRILLING CO. C.57 LICENSE NUMBER Cascade Drilling C-57 717510	7.5-2-2 TYPE OF WELL/TOTAL NUMBER 4
CITY ZIP TELEPHONE	CATHODIC
SEALING MATERIAL / ESTIMATE AMOUNT OF SEALING MATERIAL NEEDED	PROPOSED START DATE 12 2 105
Bentonite / 19 gallons - 45 gallon METHOD OF DESTRUCTION	
* Overdrill to terminal depth,	backfill w/grout, cap w/concrete
DIAGRAM OF WELL SITE (Use additional sheets and/or attachments)	1 HEREBY AGREE TO COMPLY IN EVERY RESPECT WITH ALL
3-7	REQUIREMENTS OF THE HEALTH CARE AGENCY AND WITH ALL ORDINANCES AND LAWS OF THE COUNTY OF ORANGE
8-9	AND OF THE STATE OF CALIFORNIA PERTAINING TO WELL
8-10	CONSTRUCTION, RECONSTRUCTION AND DESTRUCTION.
\\\-\\\	APPLICANTS SIGNATURE
	Kristen Daza
	949 702-8504 949 362-0290
SITE PLAN ATTACHED	PHONE NUMBER FAX NUMBER
FOR ACCOUNTING USE ONLY:	DISPOSITION OF PERMIT (DO NOT FILL IN):
DATE	APPROVED SUBJECT TO THE FOLLOWING CONDITIONS:
INTL. SI	A. NOTIFY THIS AGENCY AT LEAST 48 HOURS PRIOR TO START. B. U SUBMIT TO THE AGENCY A WELL DESTRUCTION REPORT.
APPROVAL BY OTHER AGENCIES:	PLEASE REFERENCE PERMIT NUMBER.
JURISDICTION	c.
REMARKS	DENIED
Ly middle (m)	PERMIT ISSUED BY TOLINGATION 11/30/2005
AUTHORIZED SIGNATURE DATE	PRINT NAME PRINT NAME PRINT NAME PRINT NAME

APPLICATION FOR WELL DESTRUCTION PERMIT

ORANGE COUNTY MEALTH CARE AGENCY ENVIRONMENTAL HEALTH DIVISION

2000 E. EDINGER AVENUE SANTA ANA, CA 92705-4720 (714) 697-3600 X: (714) 972-0749

CITY O 1 A	DATE 12/5/05 \$
Janta Ana	DATE 12/5/05 RED (2085 NAME OF CONSULTING FIRM Delta Environmenta/ BUSINESS ADDRESS 27/4/ Aligo Crek, St. 270
WELLLOCATION (ADDRESS IF AVAILABLE) VZZZ East First St, Santz Ana - A	RCO (4085
NAME OF WELLOWNER Attaitic Richfield Company	NAME OF CONSULTING FIRM Delta Ingronmental Z
ADDRESS Contents	BUSINESS ADDRESS
(COCICI POLIV)	27141 Alisa Crek, St. 270
La falora 90623 562-438-3871	Aliso Niejo 92656 949 292-4139
NAME OF DRILLING CO. C-57 LICENSE NUMBER Cascade Drilling 438-3871	WELL DEPTH 20 Feel WATER
Drwalk 20650 562-929-8176	DIAMETER 4" Inches OTHER
SEALING MATERIAL / ESTIMATE AMOUNT OF SEALING MATERIAL NEEDED	PROPOSED START DATE 12/2/05
METHOD OF DESTRUCTION	
overduill to terminal depth, back fill	with grout, chip seal, parch
surface w/concrete	
l	
DIAGRAM OF WELL SITE (Use additional shorts and/or attachments)	I HEREBY AGREE TO COMPLY IN EVERY RESPECT WITH ALL
	REQUIREMENTS OF THE HEALTH CARE AGENCY AND WITH ALL ORDINANCES AND LAWS OF THE COUNTY OF GRANGE
VW-2	AND OF THE STATE OF CALIFORNIA PERTAINING TO WELL
	CONSTRUCTION, RECONSTRUCTION AND DESTRUCTION.
	Rast 100 12/5/00
	APPLICANT'S SIGNATURE DATE
	Kristen Diza
	949 292-4139 362-0290
SITE PLAN ATTACHED	PHONE NUMBER FAX NUMBER
FOR ACCOUNTING USE ONLY:	DISPOSITION OF PERMIT (DO NOT FILL IN):
HSO ND. 1975(0) CHECK NO. 5075	APPROVED SUBJECT TO THE FOLLOWING CONDITIONS:
DATE 12/5/65 AMOUNT 11/-	A. D NOTIFY THIS AGENCY AT LEAST 48 HOURS PRIOR TO START.
INT	B. SUBMIT TO THE AGENCY A WELL DESTRUCTION REPORT.
APPROVAL BY OTHER AGENCIES:	PLEASE REFERENCE PERMIT NUMBER. C. A OTHER ALCHONG TRAFFIC BOX
JURISDICTION	A:-50,
REMARKS	DENIED
	1
	PERMIT ISSUED BY
AUTHORITY NOUN Man	DAN YOKOYAWA (714)433-6289
AUTHORIZED SIGNATURE DATE	PRINT NAME

APPLICATION FOR WELL DESTRUCTION PERMIT

ORANGE COUNTY HEALTH CARE AGENCY ENVIRONMENTAL HEALTH DIVISION

2009 E. EDINGER AVENUE SANTA ANA, CA 92705-4720 (714) 667-3600 FAX: (714) 972-0749

CITY Santa ang	DATE 1/23/06
WELL LOCATION (ADDRESS IF AVAILABLE) . 1222 East First St	AR10 6085
NAME OF WELL OWNER Rich Field Co.	NAME OF CONSULTING FIRM
ADDRESS Conterporate	BUSINESS ADDRESS 27/41 aliso Creek Rd =270
CITY Palma 90,23 714.228.6783	CITY TIP TELEPHONE
NAME OF DRILLING CO. C-57 LICENSE NUMBER	WELL DEPTH Feet □ WATER
Norwalk 90650 562-929-8176	CATHODIC B-6 MONITORING VAIOSE B-8 CATHODIC B-6 MONITORING VAIOSE B-8
SEALING MATERIAL/ESTIMATE AMOUNT OF SEALING MATERIAL NEEDED Ben fan te 30 gal each = 60.	PROPOSED START DATE 52/ 12/2/05
Remue grout	
DIAGRAM OF WELL SITE (Use additional sheets and/or attachments)	
See map wells B-64B-8	I HEREBY AGREE TO COMPLY IN EVERY RESPECT WITH ALL REQUIREMENTS OF THE HEALTH CARE AGENCY AND WITH ALL ORDINANCES AND LAWS OF THE COUNTY OF ORANGE
	AND OF THE STATE OF CALIFORNIA PERTAINING TO WELL CONSTRUCTION, RECONSTRUCTION AND DESTRUCTION.
·	APPLICANTS SIGNATURE DATE
	PRINT NAME
SITE PLAN ATTACHED	949-860-0209 949-362-0290
	PHONE NUMBER FAX NUMBER
HSO NO. 300/18 CHECK NO. 886	DISPOSITION OF PERMIT (DO NOT FILL IN):
HSO NO. 300/18 CHECK NO. 80.70	APPROVED SUBJECT TO THE FOLLOWING CONDITIONS:
DATE SOLO	A. NOTIFY THIS AGENCY AT LEAST 48 HOURS PRIOR TO START.
APPROVAL BY OTHER AGENCIES:	B. SUBMIT TO THE AGENCY A WELL DESTRUCTION REPORT. PLEASE REFERENCE PERMIT NUMBER.
JURISDICTION	C. DOTHER WENS WERE DESTROYED ON 12/2/05-EMERGENCY
REMARKS	DENIED WELL & ESTWITION - 7415
	AGENCY DID NOT MITNESS DESERVETION PROCESURES. MAKE SURE WELL TRAFFIC BOXES
7	MAKE SINE WELL MAFFIC BOXES
605	Dan Johnson 1/24/2006 PERMIT ISSUED BY
AUTHORIZED SIGNATURE DATE	BANYOKOYAMA (114)433-6288
DATE	PRINT NAME PHONE NUMBER